



STAPLE SOD EVERY 10 INCHES WITHIN
4 INCHES OF LEADING EDGE AND
RANDOMLY THROUGHOUT

STAPLED SOD DETAIL

NO SCALE